

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

Number SA1341GL

COPY

This certificate, issued to National Aircraft Service, Inc.  
4332 Macon Road  
Tecumseh, MI 49286

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations. (See Type Certificate Data Sheet A10SW for complete certification basis.)

Original Product — Type Certificate Number: A10SW

Make: Mitsubishi

Model: MU-2B-25, -26, -26A, -35, -36A, -40, -60

*Description of Type Design Change:*

Replace right side cockpit window with Crew Door conforming to National Aircraft Service Drawing List NA-DL1R, Rev. E, dated January 9, 1989; and installed in accordance with Installation Instructions NAD-MU2-1R, Rev. D, dated January 9, 1989; or later FAA-approved revisions of these data.

*Limitations and Conditions:*

This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. FAA-approved National Aircraft Service Airplane Flight Manual Supplement, Rev. 1, dated March 16, 1989, is required.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 15, 1988

Date issued:

Date of issuance: November 30, 1988

Date amended: March 17, 1989



By direction of the Administrator

Donald P. Michal

(Signature)  
Donald P. Michal  
Manager, Chicago Aircraft Certification Office  
ACE-115C, Central Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.