

Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate

Number SA84CH

certificate, issued to National Aircraft Service, Inc.
9133 Tecumseh-Clinton Road
Tecumseh, MI 49286

lies that the change in the type design for the following product with the limitations and conditions for as specified hereon meets the airworthiness requirements of Part 10 of the Civil Air Regulations. (See Type Certificate Data Sheet A2PC for Complete Certification Basis.)

Original Product—Type Certificate Number: A2PC
Make: Mitsubishi
Model: MU-2B, MU-2B-10, -15, -20, -25, -26, -30, -35, -36

Description of Type Design Change:

Replace Cabin Door Seal with National Aircraft Service, Inc. Door Seal, DADS01, Rev. A, dated 7-1-92 or later FAA-approved revisions, installed in accordance with National Aircraft Service, Inc. Document MU2-6, Rev. A, dated 7-1-92 or later FAA-approved revision.

Limitations and Conditions:

Approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will produce no adverse effect upon the airworthiness of that aircraft.

...certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 6, 1990

Date reissued:

Date of issuance: July 8, 1993

Date amended:



By direction of the Administrator

Charles L. Smalley
(Signature)

for Donald P. Michal, Manager
Chicago Aircraft Certification Office
(Title)

Alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.